ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone DASARAHALLI	**Ward No.** 13	**Ward Name** Mallasandra
Street ID W0177, W0095, W0093, W0180, W0182, W0181, W0179, W	**Street Name** NA, Om Shakthi Lyt 2nd Crs, 15th Crs, Vinayaka Lyt 3rd Crs	**Significant Landmark** Uchangi Temple And Mallikarjuna Swamy Temple Surro
Segment No. 13/C-W0177/S060346	**Total Length (m)** 324.45	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	102.48	77.512652	13.055093	77.512853	13.055992	Uchangi temple	8th D Cross
2	62.21	77.512724	13.052882	77.512845	13.053431	Pipeline Road	Mallikarjuna Swamy Temple Road
3	159.76	77.512590	13.053562	77.513770	13.053692	Uchangi Temple Road	Mallikarjuna Swamy Temple

Work Details

History of Road / Lane / Circles

Name of the Work Improvments To CC Roads At Mallikarjuna Swamy Temple And Shree Shakthi Bhavana Surrounding Area In Ward No.13 Shettyhalli SUb Division	**Sanctioned Estimated Amount (Rs.)** 5800000	**Sanctioned Year** 2019
Year 2018 - 2019	**Type of Work** Others	**Other Work Type**
Tender Not a Tender	**Work Details**	**Job No. / Work Code** 013-20-000070
Work Order No. BBMP/EE/DD/WO/553/2019-20	**Work Order Date** 14/02/2020	**Period of Extention**
Defect Liability Period From 31/05/2020	**Defect Liability Period To** 31/05/2021	**Multiple road involved with the same Job No/ Work Code #** Yes

Contractor Details

Name of Contractor KRIDL	**Contractor Reg No (BBMP/PWD)**	**Expenditure Booked \ Released (Rs)** 0.00
Phone No.	**E-Mail ID**	

Scanned by CamScanner

9980319812

Field Inspection Details

Number of Trees

0

Any Other Information

Name

Venkateshappa

Date of Inspection

11/01/2021

Remarks

Category	Image	Photo Remark
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0177, W0095, W0093, W0180,

Scanned by CamScanner

Designation	Approver Name	Date	Target Date	Remark
CE	CE DAS	06/03/2021	06/03/2021	Approved
EE	EE DAS	05/03/2021	06/03/2021	COMPLETED
AEE	Nageshmurthy	05/03/2021	06/03/2021	approved
AE	Venkateshappa	05/03/2021	06/03/2021	approved
AE	Venakteshappa	05/03/2021	10/02/2021	approved

2.

Da

Pai

Cas

I.

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0177, W0095, W0093, W0180,

Scanned by CamScanner